

Portes-mouvements standard Bergeon

Standard-Bergeon Werkhalter

Standard Bergeon movement holder

Porta-máquinas Bergeon estándar



7100-063/4



7100-063/4X8



7100-073/4



7100-081/4



7100-083/4



7100-101/2



7100-111/2



7100-131/4

Portes-mouvements spécifique ETA

Spezifische ETA Werkhalter

Specific ETA movement holder

Porta-máquinas ETA específica



7100-ETA-2094



7100-ETA-251.2XX



7100-ETA-251.471



7100-ETA-280.002



7100-ETA-2894



7100-ETA-2895




7100-ETA-6497



7100-ETA-7001



7100-ETA-775X



7100-ETA-901



7100-ETA-988.333



7100-ETA-A07.211



7100-ETA-E01.001



7100-ETA-G10.211



7100-ETA-G15.211

Référence Referenz Reference Referancia	Calibre Kaliber Caliber Calibre	Passage de tige Durchgang Stiel Passage stem Pasaje tallo	Poussoirs Drücker Pushers Empujadores	Vis d'appui Stützschrabe Support screw Tornillo de soporte		Base Basis Based Base
				Ø ext. mm	Ø int. mm	
7100-063/4	6 3/4 ""	1	0	0.60	0.40	Ø 31
7100-063/4X8	6 3/4 "" x 8	1	0	0.75	0.40	Ø 31
7100-073/4	7 3/4 ""	1	0	0.60	0.40	Ø 31
7100-081/4	8 1/4 ""	1	0	0.60	0.40	Ø 31
7100-083/4	8 3/4 ""	1	0	0.75	0.40	Ø 31
7100-101/2	10 1/2 ""	1	0	0.75	0.40	Ø 31
7100-111/2	11 1/2 ""	1	0	0.60	0.40	Ø 31
7100-131/4	13 1/4 ""	1	0	0.75	0.40	Ø 31

7100-ETA-2094	10 1/2 ""	1	2	0.60	0.40	Ø 31
7100-ETA-251.2XX	13 1/4 ""	1	4	0.60	0.40	Ø 31
7100-ETA-251.471	10 1/2 ""	1	2	0.90	0.40	Ø 31
7100-ETA-280.002	3 3/4 "" x 6 3/4 ""	1	0	0.75	0.40	Ø 31
7100-ETA-2894	12 1/2 ""	1	2	0.60	0.40	Ø 31
7100-ETA-2895	11 1/2 ""	1	0	0.60	0.40	Ø 31
7100-ETA-6497	16 1/2 ""	2	0	1.10	0.40	Ø 31
7100-ETA-7001	10 1/2 ""	1	0	0.90	0.40	Ø 31
7100-ETA-775X	13 1/4 ""	1	4	0.6-0.7	0.4-0.4	Ø 31
7100-ETA-901	5 1/2 "" x 6 3/4 ""	1	0	0.60	0.40	Ø 31
7100-ETA-988.333	9 3/4 "" x 11 1/2 ""	1	0	0.60	0.40	Ø 31
7100-ETA-A07.211	16 1/2 ""	1	3	0.60	0.40	Ø 31
7100-ETA-E01.001	4 7/8 ""	1	0	1.98	-	Ø 31
7100-ETA-G10.211	13 1/4 ""	1	2	-	-	Ø 31
7100-ETA-G15.211	10 1/2 ""	1	2	-	-	Ø 31